

OUT55906

multi

P 042156Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 4700.

1965 JUN 4 22 21Z

7 JUN 1965

COPIES RECEIVED		
Cy No.	Office	Act.
1	File	
2	OS	
	ADMIN	
	SEC DR	
	PLDS	
	OOD	
	PO	
	PS	
	SEC-IG	
	TID	
	PID	
	PAG	
	DIAAX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 122 WAS USED IN MISSION 8021 FLOWN ON 3 JUNE 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND RESOLUTION WAS GOOD.

B. 9R SIDE: THERE ARE SEVERAL FINE PLUS DENSITY LINES APPROXIMATELY 3 TO 3.5 INCHES FROM THE INBOARD EDGE ON FRAME 7 THROUGH FRAME 50. THERE IS A ROW OF MINUS DENSITY DOTS 4.3" FROM THE INBOARD EDGE STARTING ON APPROXIMATELY FRAME 150 THROUGHOUT THE REST OF THE MISSION. THERE IS EDGE STATIC ON THE OUTBOARD EDGE THROUGHOUT THE MISSION. ON FRAMES 92, 155 AND 231 THERE IS FOG ON THE OUTBOARD EDGE. HEAT SPLICES ARE PRESENT BETWEEN FRAMES 41/42, 47/48, 1144/1145, 1151/1152, 1208/1209, 1261/1262, 2210/2211 AND 2170/2171. THERE IS A MANUFACTURING SPLICE IN FRAME 1911.

C. 9L SIDE: THERE ARE A SERIES OF MINUS DENSITY DOTS, 1.65" APART 2.5" FROM AND PARALLEL TO THE OUTBOARD EDGE OF THE NEGATIVE IN THE FIRST 15 FRAMES OF THE MISSION. STARTING AT FRAME 63 AND

Declassification Review by NGA/DoD

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

CONTINUING TO A BREAKDOWN HEAT SPLICE IN FRAME 1053 THERE ARE PROCESSOR INDUCED EXTREMELY FINE PLUS DENSITY LINES 3.5", 4.4", 5.4", 6.1" AND 7.4" FROM AND PARALLEL TO THE MAJOR AXIS OF THE FILM. THESE LINES DO NOT DEGRADE THE INTELLIGENCE VALUE OF THE PHOTOGRAPHY AND ARE JUST DISCERNIBLE IN THE POSITIVES. BETWEEN FRAME 1053 AND 1113 SIMILAR FINE PLUS DENSITY LINES ARE DETECTABLE 4.1" AND 5.5" FROM THE INBOARD EDGE. NUMEROUS (8) HEAT SPLICES BETWEEN FRAMES INDICATE THAT ATTEMPTS WERE MADE TO ELIMINATE THE CAUSE OF THESE LINES. MANUFACTURING SPLICES ARE PRESENT IN FRAMES 53 AND 569.

D. BOTH SIDES: THE DATA BLOCK WAS NOT RECORDED ON THE FIRST FRAME. THE MISSION WAS TITLED CONSECUTIVELY FROM 1 THROUGH 2313.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY WAS GOOD.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUD COVER IS APPROXIMATELY 25 PERCENT.

S E C R E T

/END OF MESSAGE/